

Albany Township  
Annual Road Tour  
May 5, 2020

The Annual Road tour of the Albany Township Board of Supervisors met on May 5, 4 P.M. At Shady's in Albany. A bus was hired to allow for social distancing. Supervisors Tim Nierenhausen, Mary Rosen, and John Greer were present, also present, Diane Noll, Clerk.

Attached are the notes from the tour.

The following items need immediate attention:

Quaker Road-Shouldering on the West end near the County Road 54 Intersection  
Quaker Road-dips in road need repair and filled with asphalt  
20048 Rushmeyer Lake Road-East end by culvert, add black dirt to be seeded with grass seed  
205 Avenue-soft spot will need crushed cement  
245 Avenue-Mattress in ditch  
South West quarter-new gravel has been placed will need to check on the intersections being  
graveled and if road will still be graded.  
360 Street/230 Avenue-patch work needed for pot hole  
350 Street – asphalt areas need to be patched  
Sand Lake Road- dips in road need repair and filled with asphalt  
21578 Northridge Circle-remove items from Right-of-way  
35793 230 Avenue-have elevation checked for water runoff  
238 Avenue -crushed cement needed on north end

Bid to be done on the North West quarter for brush removal in right-of-ways.

A motion to have the above items completed was made by Supervisor Rosen, seconded by Supervisor Greer, motion carried unanimously.

A motion to adjourn was made by Supervisor Rosen, Seconded by Supervisor Greer, motion carried.  
Meeting adjourned at 8:15 P.M.

Respectfully Submitted,

*Diane E Noll*

Diane E Noll

Clerk/Treasurer

Approved Minutes: Tim Nierenhausen Date: June 1, 2020

*Township Board Chair*

ROAD NAME	SECTION	TYPE	INFORMATION	SIGNS/BRUSH	ACTION
201 Ave-PRIVATE	25	Gravel			
205 Ave	11	Gravel	Grading needed	Trees in ROW	
207 Ave (N CTY RD 154) Dead E	11	Gravel		Sign Twisted	
207 Ave (S of 94) Dead end	23 & 26	Black top	Kotzer Excavating responsibility		
219 Ave	15	Black top	Shouldering needs to be completed		
225 Ave	3 & 4	Gravel	Good condition, frost boil on South End		
230 Ave – Dead end	9	Gravel	Po hole in intersection w/ 360 Street	Brush in ROW	
230 Ave	16	Black top	Elevation of culvert to be measured		
235 Ave – Dead end	8 & 9	Gravel	Good Condition		
238 Ave (S of 350 St) Dead End	20	Gravel	Grading needed		2020 Gravel
238 Ave (N of 350 St) Dead End	17	Black top/Gravel	North end crushed cement needed		2020 Gravel
239 Ave	32	Gravel	Good Condition	Trees north end	
245 Ave	5 & 6	Gravel	Soft spot crushed cement needed north end		
245 Ave	7 & 8	Gravel	Good Condition		
248 Ave (N of 94)	18	Gravel	Soft spot will need crushed cement		
248 Ave (S of 94) Dead End	18	Gravel	35578 location of approach needs to be checked		2020 Gravel
249 Ave	30	Gravel	areas of soft spots will need crushed cement		2020 Gravel
249 Ave	31	Gravel			2020 Gravel
251 Ave	6	Gravel	Good Condition	Brush across from 3	
251 Ave	7	Gravel	Fence in ROW		
253 Ave	30	Black top	Pot holes need repair		
255 Ave/shared with Oak	18	Gravel	Grading needed		2020 Gravel
255 Ave/shared with Oak	19	Gravel	Grading needed		2020 Gravel
320 St/shared with Farming	32/33	Gravel		Brush in ROW	
322 St	34	Gravel	Good Condition		
325 St (W of 249 Ave)	31	Gravel	Good Condition		2020 Gravel
330 St E of Sand Lake	26/35	Black top		Brush E of Fifth Lak	
330 St-W of CR 41	32	Gravel	Good Condition		
330 St W of CR 41	33	Gravel	Good Condition	Brush N side	
330 St E of CR 41	34	Gravel	Crops planted in ROW	Brush in ROW	
334 St / share with Oak	30	Black top		Brush in ROW	
335 St Dead End-Kotzer	29	Gravel	Good Condition		
340 St(E of 41)	22&27	Gravel	Good Condition		
340 St (W of Sand Lake Rd)	22&27	City annexed			
350 St	18/19	Gravel			2020 Gravel
350 St	17/20	Gravel	Patch by culvert		2020 Gravel
350 St	16/21	Black top	Pot holes need repair		
355 St	16	Gravel			2020 Gravel
360 St (E of 238)	10 & 15	Black top	2020 Rebuilt		
360 St (W of 238)	15/10	Gravel			
360 St (W of 238)	16/9	Gravel			
360 St (W of 238)	17/8	Gravel	Mattress in ROW/Grading needed		
360 St (W of 238)	18/7	Gravel	Grading needed	Brush in ROW	
365 St	7	Gravel			
372 St – Dead end	5	Gravel		Brush in ROW	
373 St – Dead end	6	Gravel	Good Condition	Brush in ROW W End	
375 St – Dead end	6	Gravel		Brush in ROW	
380 St (share w/Krain)	2	Gravel	Good Condition	ROW needs clean	
380 St (share w/Krain)	2 & 3	Gravel	Krain Township responsible		
Fifth Lake Road	35 & 36	Black top	Good Condition		
Meadowview Dr	23	Black top			
Northridge Cir	34	Gravel		Brush and Debris i	
Northwind Rd	35	Black top	Good Condition		
Orchard Rd	28	Gravel	Grading needed	Brush in ROW	
Orchard Rd	29	Gravel	Grading needed	Brush in ROW	
Pine Lake Road-Private	12	Gravel			
Pioneer View Road	10	Gravel	Grading needed		
Quaker Road	13	Black top	Bridge has tree blocking	Sapplings in ROW	
Quaker Road	14	Black top	Shouldering at Int. of County rd 54		
Rushmeyer Lake Road	13 & 24	Black top	Work to be done by culvert on east end		
Saint Anna Drive	1	Gravel	Good Condition – check rocks in road		
Saint Anna Drive	2	Gravel		Brush in ROW	
Sand Lake Rd	27 & 26	Black top	Good Condition		
Sand Lake Rd	34 & 35	Black top	Dip in road on S end needs repair		
Trestle Ridge RD(not Township Road)					